Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Advanced Disposal Services Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Douglas Ray	Phone:	630-373-0364		
Inspector:	Andrew Nowak	Email:	douglas.ray@advanceddisposal.com		
Date/Times:	10/22/20 7:30 AM	Interviewed:	Douglas Ray (by email)		
Weather:	rainy/overcast 50F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

IEPA-DIVISION OF RECORDS MANAGEMENT RELEASABLE

FEB 16 2021

REVIEWER: SAB

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/22/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Nowak conducted a solid waste inspection of Veolia-Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. No one was interviewed during the inspection. The weather was rainy/overcast and about 50°F.

The site is approximately one acre in size and contains an office trailer, scales, and a transfer station building. The eastern and western neighboring properties are residential properties, the north end neighbors another company, and the south end of the site accesses Church Street. MSW is accepted at the site. No recycling is accepted. If batteries are found, they are brought to the Northbrook transfer station.

Engineer Nowak toured the site. A garbage truck was weighing in on the scale near the site entrance. Approaching the transfer station building, Engineer Nowak observed a small oil sheen running just north of a storm sewer, but it had not yet reached the sewer. The staff member operating in the scale office, Xavier, told Engineer Nowak he would tell another staff member to get oil dry from the offices across the street and clean up the spill right away.

Engineer Nowak observed piles of MSW in the transfer station building. One side was for garbage trucks and the other side was for smaller hauling trucks. The building's misting system was operating during the inspection. Engineer Nowak observed a fire extinguisher certified by Cintas in November 2019.

A staff member was picking up litter throughout the site. Garbage bins lined the west end wall to collect litter from the site. On the west side of the site, there was a tire bin. Engineer Nowak observed seven tires in the bin. Engineer Nowak observed the site had completed the construction of the tarping station.

After the inspection, Engineer Nowak drove along the neighboring properties to the east and north and did

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Andrew Nowak

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/22/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Observations and Comments (continued):

not observe a malodor.

Mr. Douglas Ray sent Engineer Nowak site totals after the inspection. In September 2020, the site received 11,608.54 tons of MSW and 4.74 tons of C&D material, while 11,467.58 tons of MSW were outbound from the site. The C&D material leaves the site with the MSW. No mattresses or tires were received during this period.

No malodor, runoff, noise, litter, mud, or dust were present.


No violations were observed during the inspection.

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/22/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Site Map


N




COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/22/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Photograph Log




Photograph No.:	1	Direction:	North
Description:	View of the site entrance		




Photograph No.:	2	Direction:	North
Description:	View of the site scale		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/22/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	3	Direction:	North
Description:	View of transfer station building		




Photograph No.:	4	Direction:	North
Description:	View of a garbage truck depositing MSW and the MSW piles		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/22/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	5	Direction:	South
Description:	View of fire extinguisher		




Photograph No.:	6	Direction:	South
Description:	View of the tires		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/22/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	7	Direction:	North
Description:	View of the storm sewer		



Photograph No.:	8	Direction:	West
Description:	View of the tarping station		