Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Advanced Disposal Services Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Douglas Ray	Phone:	630-373-0364		
Inspector:	Travis Wood	Email:	douglas.ray@advanceddisposal.com		
Date/Times:	1/6/2021 10:00 AM	Interviewed:	Douglas Ray		
Weather:	Mostly sunny 34°F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

IEPA-DIVISION OF RECORDS MANAGEMENT
RELEASABLE

MAY 11 2021

REVIEWER: SAB

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/6/2021	Time:	10:00 am
Inspector:	Travis Wood			Badge No.:	122

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Wood conducted a solid waste inspection of Veolia-Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. Douglas Ray was interviewed during the inspection, which took place on a mostly sunny 34°F morning.

The site is approximately one acre in size and contains an office trailer, scale building, scales, and a transfer station building. An office where records are kept is located south of the site, on the opposite side of Church Street. The eastern and western neighboring properties are residential properties, the north end neighbors another company, and the south end of the site accesses Church Street. MSW is accepted at the site, and is taken to the Zion Landfill. No recycling is accepted. If batteries are found, they are brought to the Northbrook transfer station.

Engineer Wood observed very little MSW in the transfer station building. One side was for garbage trucks and the other side was for smaller hauling trucks. At the time of inspection, small hauling trucks were dumping material onto the tipping floor. One garbage truck was preparing to empty MSW onto floor. Engineer Wood observed a fire extinguisher serviced by Cintas in March of 2020 as well as a sprinkler system maintained by Cintas.

The odor control misting system was not operating as it has been winterized for the season. No odor was detected at the time of the inspection. Engineer drove through the adjacent residential areas to check for any odor, none was observed. Mr. Ray explained that if an odor is noticed, the staff will disperse an odor control powder by a hand cranked piece of equipment.

A staff member was seen picking up litter along Church Street on the south border of the site. Mr. Ray explained that the crew patrols the townhomes to the east, and along

On the west side of the site, a covered tire bin containing roughly 16 tires was observed; Shred all picks up the tires from the site.

Continued on next page...

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Travis Wood

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/6/2021	Time:	10:00 am
Inspector:	Travis Wood			Badge No.:	122

Observations and Comments (continued):

Mr. Douglas sent Engineer Wood site totals for the month of December 2020. A total of 10,244.81 tons of MSW entered the facility and 10,123.37 left the facility.

No malodor, runoff, mud, or dust were present. No violations were observed during the inspection.


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/6/2021	Time:	10:00 am
Inspector:	Travis Wood			Badge No.:	122

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/6/2021	Time:	10:00 am
Inspector:	Travis Wood			Badge No.:	122

Photograph Log




Photograph No.:	1	Direction:	North
Description:	View of site entrance, no litter observed off site		




Photograph No.:	2	Direction:	Northeast
Description:	View of site scale and scale office		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/6/2021	Time:	10:00 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	3	Direction:	Northeast
Description:	View of staff patrolling area adjacent to site for litter		




Photograph No.:	4	Direction:	North
Description:	View of transfer station building		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/6/2021	Time:	10:00 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	5	Direction:	Northeast
Description:	View of material dropped off by small trucks		




Photograph No.:	6	Direction:	North
Description:	View of tipping floor, garbage truck with incoming load		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/6/2021	Time:	10:00 am
Inspector:	Travis Wood			Badge No.:	122



Photograph No.:	7	Direction:	South
Description:	View inside tire bin		



Photograph No.:	8	Direction:	East
Description:	View of outbound truck waiting to be loaded.		