Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #: 0310810003	Region: 2 - Des Plaines
Site Name:	Advanced Disposal Services Transfer Station		
Site Address:	1711 Church Street	City:	Evanston
Site Contact:	Douglas Ray	Phone:	630-373-0364
Inspector:	Travis Wood	Email:	douglas.ray@advanceddisposal.com
Date/Times:	9/15/20 8:00 AM	Interviewed:	Douglas Ray (by email)
Weather:	Sunny 62F	Complaint #:	N/A

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

IEPA-DIVISION OF RECORDS MANAGEMENT
RELEASABLE
DEC 28 2020
REVIEWER: EMI

Operational Status (permitted and permit-exempt sites):

Operating ☐
Closed/Not Certified ☐
Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐
Closed ☐

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Wood conducted a solid waste inspection of Veolia-Evanston Transfer.Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. Douglas Ray was interviewed during the inspection. The weather was sunny and 62°F.

The site is approximately one acre in size and contains an office trailer, scale building, scales, and a transfer station building. An office where records are kept is located south of the site, on the opposite side of Church Street. The eastern and western neighboring properties are residential properties, the north end neighbors another company, and the south end of the site accesses Church Street. MSW is accepted at the site, and is taken to the Zion Landfill. No recycling is accepted. If batteries are found, they are brought to the Northbrook transfer station.

Engineer Wood observed piles of MSW in the transfer station building. One side was for garbage trucks and the other side was for smaller hauling trucks. At the time of inspection, a truck was adding to the larger of the two piles. The building's misting system, was operating during the inspection. Mr. Ray explained that the misters are used the entire time the facility is accepting waste. Engineer Wood observed a fire extinguisher certified September 2020 as well as a sprinkler system maintained by Cintas.

A staff member was seen picking up litter along Church Street on the south border of the site. Mr. Ray explained that the crew patrols the townhomes to the east, and along Church Street to the west. Garbage bins lined the west end wall to collect litter from the site. On the west side of the site, a tire bin full of tires was observed. Mr. Ray informed the engineers that an order was put in that day for Shred All to pick up the bin.

Engineer Wood observed the stormwater detention facility located on the north end of the site. No water was observed in the facility; Mr. Ray mentioned that the facility is functioning but not draining as designed and

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Travis Wood

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122

Observations and Comments (continued):

Mr. Ray provided copies of vector control reports while on site. Men in Black Pest Control Services were on site on 8/6/2020 and on 8/20/2020. During these visits, bait stations were refilled and traps were cleaned and reset.

After the inspection, Engineer Wood drove along the neighboring properties to the East, North, and West and did not observe a malodor.

Mr. Douglas will sent Engineers Nowak and Wood site totals for the month of August as well as complaint logs for the site. In August, a total of 10,969.09 tons of MSW entered the facility and 10,923.74 left the facility. No complaints were logged for the month.

No malodor, runoff, mud, or dust were present.

No violations were observed during the inspection.


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122

Photograph Log



Photograph No.:	1	Direction:	North
Description:	View of truck on scale.		



Photograph No.:	2	Direction:	North
Description:	View of transfer station building		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	3	Direction:	North
Description:	View of truck adding to MSW pile.		




Photograph No.:	4	Direction:	North
Description:	View of misting system in use.		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	5	Direction:	Southeast
Description:	View of loading bay for outgoing MSW		




Photograph No.:	6	Direction:	Southeast
Description:	View of stormwater detention facility		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	7	Direction:	Southeast
Description:	View of mister system tank (blue) and hand mister containers.		




Photograph No.:	8	Direction:	South
Description:	View of tire bin		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	9/15/20	Time:	8:00 AM
Inspector:	Travis Wood			Badge No.:	122



Photograph No.:	9	Direction:	West
Description:	View of double walled fuel tank and up to date fire extinguisher		



Photograph No.:	10	Direction:	Southeast
Description:	View of scale house		