Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Advanced Disposal Services Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Douglas Ray	Phone:	630-373-0364		
Inspector:	Travis Wood	Email:	douglas.ray@advanceddisposal.com		
Date/Times:	7/12/2021 7:30 AM	Interviewed:	Douglas Ray		
Weather:	Cloudy 69°F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

IEPA-DIVISION OF RECORDS MANAGEMENT
RELEASABLE
OCT 27 2021
REVIEWER: SAB

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Wood conducted a solid waste inspection of Veolia-Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. No one was available for interview at the time of inspection.

The site is approximately one acre in size and contains an office trailer, scale building, scales, and a transfer station building. An office where records are kept is located south of the site, on the opposite side of Church Street. The eastern and western neighboring properties are residential properties, the north end neighbors another company, and the south end of the site accesses Church Street. MSW is accepted at the site, and is taken to the Zion Landfill. No recycling is accepted. If batteries are found, they are brought to the Northbrook Transfer Station.

Engineer Wood observed MSW in the transfer station building. One side was for garbage trucks and the other side was for smaller hauling trucks. At the time of inspection, garbage trucks were observed tipping material in the transfer station building. An outbound truck was also being loaded with MSW.

The odor control misting system was operating at the time of inspection; sprayers were observed above the bay doors and inside the transfer station building. No odor was detected at the time of the inspection. Engineer drove through the adjacent residential areas to check for any odor, none was observed. If an odor is noticed outside of the transfer station building, the staff will disperse an odor control powder by a hand cranked piece of equipment.

On the west side of the site, a covered tire bin was observed. Mr. Ray said that Pomp's tires, who services the company's fleet of trucks, has started to pick up any used tires when they are on site each month. The tires are picked up on the first Thursday of each month. Tires used to be sent to Shred-all.

Continued on next page...

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Travis Wood

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122

Observations and Comments (continued):

Engineer requested site totals via email and will update the report when the information is obtained.

No malodor, runoff, mud, or dust were present. No violations were observed during the inspection.


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122

Photograph Log




Photograph No.:	1	Direction:	East
Description:	View of roadway adjacent to site, no litter observed		




Photograph No.:	2	Direction:	Northeast
Description:	View of site entrance free from litter		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	3	Direction:	Northeast
Description:	View of scale and scale house		




Photograph No.:	4	Direction:	Northwest
Description:	View of load checking and tarping platform		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	5	Direction:	Northeast
Description:	View of transfer station building		




Photograph No.:	6	Direction:	East
Description:	View of odor misting system in operatoin		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	7	Direction:	West
Description:	View of site activities and MSW pile in transfer station building		




Photograph No.:	8	Direction:	South
Description:	View of tire storage bin		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/12/2021	Time:	7:30 am
Inspector:	Travis Wood			Badge No.:	122



Photograph No.:	9	Direction:	Northwest
Description:	View of fueling area and spill kit		



Photograph No.:	10	Direction:	Southeast
Description:	View of outbound truck in bay waiting to be loaded		