Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

01

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Advanced Disposal Services Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Douglas Ray	Phone:	630-373-0364		
Inspector:	Travis Wood	Email:	douglas.ray@advanceddisposal.com		
Date/Times:	01/10/2022 8:15 AM	Interviewed:	Douglas Ray		
Weather:	Sunny 15°F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

IEPA-Division of Records Management Releasable

MAY 12 2022

Reviewer KAP

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Wood conducted a solid waste inspection of Veolia-Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. Mr. Douglas Ray was interviewed via phone as he was not available for interview at the time of inspection, which took place on a sunny 15°F morning.

The site is approximately one acre in size and contains an office trailer, scale building, scales, and a transfer station building. An office where records are kept is located south of the site, on the opposite side of Church Street. The eastern and western neighboring properties are residential properties, the north end neighbors another company, and the south end of the site accesses Church Street. MSW is accepted at the site and is taken to the Zion Landfill. No recyclable material or yard waste is accepted. If batteries are found, they are brought to the Northbrook Transfer Station.

Engineer Wood observed MSW in the transfer station building. One side was for garbage trucks and the other side was for smaller hauling trucks. At the time of inspection, garbage trucks were observed tipping material in the transfer station building. An outbound truck was also being loaded with MSW.

The odor control misting system was operating at the time of inspection; sprayers were observed above the bay doors and inside the transfer station building. No odor was detected at the time of the inspection. Engineer drove through the adjacent residential areas to check for any odor, none was observed. If an odor is noticed outside of the transfer station building, the staff will disperse an odor control powder by a hand cranked piece of equipment.

On the west side of the site, a covered tire bin was observed; Engineer observed roughly eight used tires. Pomp's Tires picks up any used tires when they are on site each month. The tires are picked up on the first Thursday of each month.

Continued on next page...

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Travis Wood

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122

Observations and Comments (continued):

Mr. Ray provided Engineer with the site totals from the month of December 2021. The site brought in 11,797.26 ton of MSW. The site sent 1,107.92 tons of MSW to Orchard Hills landfill and 10,655.40 tons of MSW to Zion landfill. The most recent vector control inspection was conducted by Men in Black Pest Control Services on December 22, 2021.

No malodor, runoff, mud, or dust were present. No violations were observed during the inspection.


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122

Photograph Log




Photograph No.:	1	Direction:	East
Description:	View of roadway adjacent to site, no litter observed		




Photograph No.:	2	Direction:	North
Description:	View of site entrance free from litter		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	3	Direction:	Northeast
Description:	View of scale and scale house		



Photograph No.:	4	Direction:	Northwest
Description:	View of load checking and tarping platform		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	5	Direction:	Northeast
Description:	View of transfer station building		




Photograph No.:	6	Direction:	Northeast
Description:	View of small contractor truck tipping area		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122




Photograph No.:	7	Direction:	West
Description:	View of site activities and MSW pile in transfer station building		




Photograph No.:	8	Direction:	South
Description:	View of tire storage bin		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	01/10/2022	Time:	8:15 am
Inspector:	Travis Wood			Badge No.:	122



Photograph No.:	9	Direction:	Northwest
Description:	View of fueling area and spill kit		



Photograph No.:	10	Direction:	Southeast
Description:	View of outbound truck loading area		