The appearance of some of the images
Following this page is due to

Poor Quality Original Documents

and not the scanning or filming processes.

Com Microfilm Company
(217) 525-5860

Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #: 0310810003	Region: 2 - Des Plaines
Site Name:	Evanston Transfer Station		
Site Address:	1711 Church Street	City:	Evanston
Site Contact:	Steve Rooney	Phone:	847-879-1998
Inspector:	Andrew Nowak	Email:	jgonza81@wm.com
Date/Times:	1/29/24 1:32 PM	Interviewed:	Juan Gonzalez
Weather:	sunny 43°F	Complaint #:	N/A

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

IEPA-DIVISION OF RECORDS MANAGEMENT
RELEASABLE
SEP 25 2024
REVIEWER: SAB

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

RECEIVED
JUL 10 2024
IL Environmental Protection Agency
Division of Records Management

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/29/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Nowak conducted a solid waste inspection of Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. Juan Gonzalez, scale operator, was interviewed during the inspection. The weather was sunny and 43°F.

The site is approximately one acre in size and contains a scale house, scales, and a transfer station building. Bordering the site are residential neighborhoods to the east and west, a business to the north, and Church Street to the south, where the site entrance/exit is located. The site accepts MSW.

Engineer toured the site. There were two MSW piles within the transfer station building. An outgoing truck was being loaded with MSW. The site has a misting system it can use for odor control inside the transfer station building. No malodor was detected around the site at the time of inspection.

There was some light litter behind the transfer station building, with a couple items being in tree branches, as well as some litter near a sliding door along the northwest perimeter of the site. Engineer pointed out this area for site staff to address before any litter blew below the sliding door.

The site has a tire bin along the site's western wall. There were no tires at the time of inspection. To the south is the tarping station. Pest control services are provided by Orkin and the last inspection was on 1/24/24 **(Permit Cond. 11)**.

Mr. Gonzalez provided recent site totals. In December 2023, the site received 5,887.37 tons (1,188 loads) of MSW, and sent 5,794.91 tons (241 loads) of MSW to Zion Landfill.

No runoff, malodor, mud, or dust were present at the time on inspection.

The site needs to clean up the light litter around the site.

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Andrew Nowak

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/29/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑



COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/29/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128

Photograph Log



Photograph No.:	1	Direction:	North
Description:	View of MSW pile		




Photograph No.:	2	Direction:	South
Description:	View of fire extinguisher		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/29/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	3	Direction:	North
Description:	View of MSW pile and site activity		




Photograph No.:	4	Direction:	East
Description:	View of outgoing truck in the loading bay		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/29/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	5	Direction:	East
Description:	View of litter		



Photograph No.:	6	Direction:	North
Description:	View of litter		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	1/29/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	7	Direction:	South
Description:	View of the tire bin		



Photograph No.:	8	Direction:	South
Description:	View of the tarping station		