Illinois Environmental Protection Agency

Fe-01

Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Evanston Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Steve Rooney	Phone:	847-879-1998		
Inspector:	Andrew Nowak	Email:	jgonza81@wm.com		
Date/Times:	8/13/24 1:32 PM	Interviewed:	Juan Gonzalez		
Weather:	sunny 86°F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

IEPA
Division of Records Management
Releasable
MAY 21 2025
Reviewer: AMS

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/13/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Nowak conducted a solid waste inspection of Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. Juan Gonzalez, scale operator, was interviewed during the inspection. The weather was sunny and 86°F.

The site is approximately one acre in size and contains a scale house, scales, and a transfer station building. Bordering the site are residential neighborhoods to the east and west, a business to the north, and Church Street to the south, where the site entrance/exit is located. The site accepts MSW.

Engineer toured the site. There was a MSW pile within the transfer station building. The site has a misting system it can use for odor control inside the transfer station building. No malodor was detected around the site at the time of inspection. Engineer observed a fire extinguisher certified by Fox Valley Fire & Safety in January 2024.

The site has a tire bin along the site's western wall. There were four tires at the time of inspection. To the south is the tarping station. Pest control services are provided by Orkin and the last inspection was on 8/7/24 **(Permit Cond. 11)**.

Mr. Gonzalez provided recent site totals. In July 2024, the site received 7,919.31 tons (1,542 loads) of MSW and sent 7,895.58 tons (317 loads) of MSW to Zion Landfill.

No runoff, litter, malodor, mud, or dust were present at the time on inspection.

No violations were observed during the inspection.

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Andrew Nowak


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/13/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128

Site Map

Photo does not depict current conditions at the site at the time of inspection.

N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/13/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128

Photograph Log



Photograph No.:	1	Direction:	North
Description:	View of the MSW pile		




Photograph No.:	2	Direction:	East
Description:	View of retention pond		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/13/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	3	Direction:	South
Description:	View of fire extinguisher		




Photograph No.:	4	Direction:	South
Description:	View of the tires		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/13/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	5	Direction:	Southwest
Description:	View of the tarping station		



Photograph No.:	6	Direction:	Northeast
Description:	View of the transfers station building		

Illinois EPA FOIA Exemption Reference Sheet

SID: 15372

Agency ID: 170000450884 Media File Type: LAND
Bureau ID: 0310810003
Site Name: Veolia-Evanston TS
Site Address1: 1711 Church St
Site Address2:
Site City: Evanston State: IL Zip: 60201-

This record has been determined to be partially or wholly exempt from public disclosure

Exemption Type:

Redaction

Exempt Doc #: 25 **Document Date:** 8 /13/2024 **Staff:** AMS


Document Description: TRANSFER/STORAGE INSPECTION

Category ID: 01 **Category Description:** FIELD OPERATIONS/INSPECTIONS **Exempt Type:** Redaction

Permit ID: **Date of Determination:** 5 /21/2025

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/13/24	Time:	1:32 PM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	7	Direction:	North
Description:	View of the scales, office, and site		