Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #: 0310810003	Region: 2 - Des Plaines
Site Name:	Advanced Disposal Services Transfer Station		
Site Address:	1711 Church Street	City:	Evanston
Site Contact:	Douglas Ray	Phone:	630-373-0364
Inspector:	Andrew Nowak	Email:	douglas.ray@advanceddisposal.com
Date/Times:	8/11/20 7:30 AM	Interviewed:	Douglas Ray (by email)
Weather:	sunny 79F	Complaint #:	N/A

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

IEPA - DIVISION OF RECORDS MANAGEMENT
RELEASABLE
NOV 24 2020
REVIEWER: JMR

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/11/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Nowak conducted a solid waste inspection of Veolia-Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. No one was interviewed during the inspection. The weather was sunny and about 79°F.

The site is approximately one acre in size and contains an office trailer, scales, and a transfer station building. A scale being repaired during the last inspection has been fixed. The eastern and western neighboring properties are residential properties, the north end neighbors another company, and the south end of the site accesses Church Street. MSW is accepted at the site. No recycling is accepted at the Site. If batteries are found, they are brought to the Northbrook transfer station.

Engineer Nowak observed piles of MSW in the transfer station building. One side was for garbage trucks and the other side was for smaller hauling trucks. The building's misting system was operating during the inspection. Engineer Nowak observed a fire extinguisher certified by Cintas in November 2019.

A staff member was picking up litter throughout the site. Garbage bins lined the west end wall to collect litter from the site. On the west side of the site, there was a tire bin. Engineer Nowak observed tires in the bin.

The pieces for the inspection station had also been piled next to the concrete pad previously observed onsite. After the inspection, Engineer Nowak confirmed at the Des Plaines IEPA office that a previous supplemental permit had approved the construction and use of the inspection station (Supplemental Permit No. 2010-461-SP).

After the inspection, Engineer Nowak drove along the neighboring properties to the east and north and did

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Andrew Nowak

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/11/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Observations and Comments (continued):

not observe a malodor.

Mr. Douglas Ray sent Engineer Nowak site totals after the inspection. In July 2020, the site received 12,089.50 tons of MSW, while 11,958.57 tons of MSW were outbound from the site. No mattresses or tires were received during this period.

No malodor, runoff, mud, or dust were present.


No violations were observed during the inspection.

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/11/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Site Map


N



COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/11/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128

Photograph Log




Photograph No.:	1	Direction:	Northeast
Description:	View of the site entrance		




Photograph No.:	2	Direction:	East
Description:	View of the site hours and unauthorized materials		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/11/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	3	Direction:	Northeast
Description:	View of transfer station building		



Photograph No.:	4	Direction:	Northwest
Description:	View of an outgoing truck being covered prior to exiting the site		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/11/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	5	Direction:	Northwest
Description:	View of the misting system		




Photograph No.:	6	Direction:	Northeast
Description:	View of an MSW pile		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT & SUSTAINABILITY

Facility:	Veolia-Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	8/11/20	Time:	7:30 AM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	7	Direction:	North
Description:	View of MSW piles		



Photograph No.:	8	Direction:	South
Description:	View of the tire bin		