Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Evanston Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Steve Rooney	Phone:	847-879-1998		
Inspector:	Andrew Nowak	Email:	ahartgrav@wm.com		
Date/Times:	10/30/23 11:17 AM	Interviewed:	Amy Hartgraves		
Weather:	clear 40°F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

RECEIVED
MAR 15 2024
IL. Environmental Protection Agency
SPRINGFIELD REGIONAL OFFICE

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

IEPA-Division of Records Management
Releasable
MAY 03 2024

Reviewer: KKN

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/30/23	Time:	11:17 AM
Inspector:	Andrew Nowak			Badge No.:	128

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Nowak conducted a solid waste inspection of Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. Amy Hartgraves, scale operator, was interviewed during the inspection. The weather was clear and 40°F.

The site is approximately one acre in size and contains a scale house, scales, and a transfer station building. Bordering the site are residential neighborhoods to the east and west, a business to the north, and Church Street to the south, where the site entrance/exit is located. The site accepts MSW.

Engineer toured the site. There was one main MSW pile and some scattered MSW within the transfer station building. A front-loader was removing MSW and placing it into an outgoing truck, which was in the loading dock. Engineer observed a fire extinguisher certified by Fox Valley Fire and Safety in July 2023 **(Permit Cond. 16)**. The site has a misting system it can use for odor control inside the transfer station building. No malodor was detected around the site at the time of inspection.

The site has a tire bin along the site's western wall. There were no tires at the time of inspection. To the south is the tarping station. Pest control services are provided by Orkin and the last inspection was on 10/18/23 **(Permit Cond. 11)**.

Engineer observed a bag of trash that appeared to have fallen off a garbage truck at the site entrance/exit. By the time Engineer informed Ms. Hartgraves of the litter, site staff had cleaned up the bag. Engineer observed the garbage bag was no longer near the site entrance/exit upon leaving the site.

No runoff, malodor, litter, mud, or dust were present at the time on inspection.

No violations were observed during the inspection.

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Andrew Nowak

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/30/23	Time:	11:17 AM
Inspector:	Andrew Nowak			Badge No.:	128

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/30/23	Time:	11:17 AM
Inspector:	Andrew Nowak			Badge No.:	128

Photograph Log




Photograph No.:	1	Direction:	North
Description:	View of the site entrance/exit and garbage bag		




Photograph No.:	2	Direction:	North
Description:	View of the site		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/30/23	Time:	11:17 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	3	Direction:	Northeast
Description:	View of MSW		




Photograph No.:	4	Direction:	North
Description:	View of MSW pile and site activity		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/30/23	Time:	11:17 AM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	5	Direction:	East
Description:	View of the outgoing truck in the loading dock		



Photograph No.:	6	Direction:	East
Description:	View of retention pond behind the transfer station building		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	10/30/23	Time:	11:17 AM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	7	Direction:	Southeast
Description:	View of the tarping station		



Photograph No.:	8	Direction:	Southwest
Description:	View of the area previously containing a garbage bag		