Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Evanston Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Doug Ray	Phone:	630-373-0364		
Inspector:	Andrew Nowak	Email:	ahartgrav@wm.com		
Date/Times:	6/23/23 8:47 AM	Interviewed:	N/A		
Weather:	sunny 72°F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

IEPA
Division of Records Management
Releasable

NOV 15 2023

Reviewer: MDB

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

Summary of Apparent Violation(s)

Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/23/23	Time:	8:47 AM
Inspector:	Andrew Nowak			Badge No.:	128

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Nowak conducted a solid waste inspection of Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. No one was available for interview at the time of inspection. The weather was sunny and 72°F.

The site is approximately one acre in size and contains a scale house, scales, and a transfer station building. Bordering the site are residential neighborhoods to the east and west, a business to the north, and Church Street to the south, where the site entrance/exit is located. The site accepts MSW. Batteries removed from incoming MSW are brought to Northbrook Transfer Station and tires are put into a bin on the western portion of the site. .

Engineer toured the site. There were two piles of MSW within the transfer station building. No material was being deposited by incoming trucks or loaded into outgoing trucks at the time of inspection. Engineer observed a fire extinguisher certified in 2023. A misting system for odor control was spraying inside the transfer station.

There was no outgoing truck in the loading dock at the time of inspection. Engineer observed the tire bin, which did not contain any tires. The site has a tarping station south of the tire bin. Pest control services are provided by Orkin and the last report was from 6/15/23.

In May 2023, the sit received 8,220.08 tons (1,826 loads) of MSW. Outgoing in May 2023 were 7,458.56 tons (308 loads) to Zion Landfill and 704.90 (31 loads) to Orchard Hills Landfill.

No runoff, malodor, litter, mud, or dust were present at the time on inspection.

No violations were observed during the inspection.

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Andrew Nowak


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/23/23	Time:	8:47 AM
Inspector:	Andrew Nowak			Badge No.:	128

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/23/23	Time:	8:47 AM
Inspector:	Andrew Nowak			Badge No.:	128

Photograph Log




Photograph No.:	1	Direction:	Northeast
Description:	View of the site entrance		




Photograph No.:	2	Direction:	North
Description:	View of the site		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/23/23	Time:	8:47 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	3	Direction:	Northeast
Description:	View of MSW pile		




Photograph No.:	4	Direction:	North
Description:	View of MSW pile and odor control misting system		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/23/23	Time:	8:47 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	5	Direction:	East
Description:	View of retention pond behind the transfer station building		




Photograph No.:	6	Direction:	East
Description:	View of the loading dock		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/23/23	Time:	8:47 AM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	7	Direction:	Southeast
Description:	View of the tire bin		



Photograph No.:	8	Direction:	South
Description:	View of tarping station		