The appearance of some of the images
Following this page is due to

Poor Quality Original Documents

and not the scanning or filming processes.

Com Microfilm Company
(217) 525-5860

Illinois Environmental Protection Agency
Delegated Agency Solid Waste Program
Transfer/Storage Inspection

County:	Cook	BOL #:	0310810003	Region:	2 - Des Plaines
Site Name:	Evanston Transfer Station				
Site Address:	1711 Church Street	City:	Evanston		
Site Contact:	Steve Rooney	Phone:	847-879-1998		
Inspector:	Andrew Nowak	Email:	jgonza81@wm.com		
Date/Times:	6/21/24 11:47 AM	Interviewed:	Juan Gonzalez		
Weather:	sunny 83°F	Complaint #:	N/A		

Owner Mailing Address

The Advanced Disposal Service SW Midwest LLC
1712 Church Street
Evanston, IL 60201

Operator Mailing Address

Evanston Transfer Station
1711 Church Street
Evanston, IL 60201

Chief Operator (conduct) Mailing Address (if applicable)

N/A

Certified Operator (competency) Mailing Address (if applicable)

N/A

Permit:

DE: OP: 1984-2-DE/OP; 2013-005-SP SigMod: Current Mod or SP:

Expiration Date:

☐ Exempt per §21(d)(1)

Operational Status (permitted and permit-exempt sites):

Operating ☐

Closed/Not Certified ☐

Closed/Date Certified:

Operational Status (unpermitted sites):

Operating ☐

Closed ☐

IEPA-Division of Records Management
Releasable

APR 15 2025

Reviewer: KKN

Summary of Apparent Violation(s)			
Status	Date	Violation	Explanation

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/21/24	Time:	11:47 AM
Inspector:	Andrew Nowak			Badge No.:	128

Inspection Report

Inspection Type:

☐Complaint ☐Commercial ☐Industrial ☒Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Engineer Nowak conducted a solid waste inspection of Evanston Transfer Station to determine site compliance with permit 1984-2-DE/OP; 2013-005-SP and applicable regulations. Juan Gonzalez, scale operator, was interviewed during the inspection. The weather was sunny and 83°F.

The site is approximately one acre in size and contains a scale house, scales, and a transfer station building. Bordering the site are residential neighborhoods to the east and west, a business to the north, and Church Street to the south, where the site entrance/exit is located. The site accepts MSW.

Engineer toured the site. There were two MSW piles within the transfer station building. A garbage truck was depositing MSW inside the transfer station building. The site has a misting system it can use for odor control inside the transfer station building, which was in operation during the inspection. No malodor was detected around the site at the time of inspection. Engineer observed a fire extinguisher certified by Fox Valley Fire & Safety in January 2024.

The site has a tire bin along the site's western wall. There was one tire at the time of inspection. To the south is the tarping station. Pest control services are provided by Orkin and the last inspection was on 6/19/24 **(Permit Cond. 11)**.

Mr. Gonzalez provided recent site totals. In May 2024, the site received 7,679.36 tons (1,433 loads) of MSW and sent 48.31 tons (2 loads) of MSW to Orchard Hills Landfill and 7,535.37 tons (305 loads) of MSW to Zion Landfill.

No runoff, litter, malodor, mud, or dust were present at the time on inspection.

No violations were observed during the inspection.

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Andrew Nowak


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/21/24	Time:	11:47 AM
Inspector:	Andrew Nowak			Badge No.:	128

Site Map

Photo does not depict current conditions at the site at the time of inspection.

N ↑




COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/21/24	Time:	11:47 AM
Inspector:	Andrew Nowak			Badge No.:	128

Photograph Log




Photograph No.:	1	Direction:	North
Description:	View of the smaller hauler MSW		



Photograph No.:	2	Direction:	North
Description:	View of MSW pile and site activity		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/21/24	Time:	11:47 AM
Inspector:	Andrew Nowak			Badge No.:	128




Photograph No.:	3	Direction:	South
Description:	View of fire extinguisher		



Photograph No.:	4	Direction:	East
Description:	View of loading dock		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/21/24	Time:	11:47 AM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	5	Direction:	East
Description:	View of the retention pond		




Photograph No.:	6	Direction:	South
Description:	View of the tire		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	6/21/24	Time:	11:47 AM
Inspector:	Andrew Nowak			Badge No.:	128



Photograph No.:	7	Direction:	South
Description:	View of the tarping station		



Photograph No.:	8	Direction:	North
Description:	View of the scale and site		