F05-01

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/15/25	Time:	10:45 AM
Inspector:	Archie Tolar			Badge No.:	122

Inspection Report

Inspection Type:

☒Complaint ☐Commercial ☐Industrial ☐Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Inspector Tolar conducted a compliance inspection of Evanston Transfer Station. Juan Gonzalez, scale operator, was on vacation. Oscar Reyes yard attendant was interviewed during the inspection. The weather was sunny and 82°F. There have been multiple complaints filed for smell at the site. The site had installed new misters, and all systems were in operation. There was a pleasant aroma, and the sprayers could be seen spraying the deodorizer.

Inspector Tolar drove within a ½ block radius to determine if there was smells outside of the immediate area of the site. There was no evidence of smell or maldor at the site during the inspection. The site was found to be complying at the time of the inspection. Inspector Tolar observed a small amount of litter during the inspection. Oscar is typically the person who picks up the litter, as he was the scale operator during Juan's absence. Oscar will clean the site at the end of each day until Juan returns.

The site is approximately one acre in size and contains a scale house, scales, and a transfer station building. Bordering the site are residential neighborhoods to the east and west, a business to the north, and Church Street to the south, where the site entrance/exit is located. The site accepts MSW.

Inspector Tolar followed up with Larry Stallings, District Manager Waste Management. Larry has installed the new misting system and is open to proactive improvements if any issues arise.

Orkin serviced the location on July 22nd, 2025.

Outbound Tonnage for MSW for June 2025 was 7,214.33 tons (Zion Landfill & Orchard Hills)

Inbound Tonnage for MSW for June 2025 was 7425.07 tons

There were 10 tires in the storage bin. (Pomps). This site will continue to be monitored on a regular basis to assure compliance.

RECEIVED
JAN 06 2026

IEPA
Division of Records Management
Releasable

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Archie Tolar

JAN 26 2026

Reviewer: AMS


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/15/25	Time:	10:45 AM
Inspector:	Archie Tolar			Badge No.:	122

Site Map

Photo does not depict current conditions at the site at the time of inspection.

N ↑



COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/15/25	Time:	10:45 AM
Inspector:	Archie Tolar			Badge No.:	122

Photograph Log




Photograph No.:	1	Direction:	South
Description:	West of a storm water sewer cover that is clean and free of debris		




Photograph No.:	2	Direction:	Northwest
Description:	West of gas tank on site		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/15/25	Time:	10:45 AM
Inspector:	Archie Tolar			Badge No.:	122




Photograph No.:	3	Direction:	North
Description:	View of site misters spraying deodorizer		




Photograph No.:	4	Direction:	North
Description:	View of bait stations along the foundation wall		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/15/25	Time:	10:45 AM
Inspector:	Archie Tolar			Badge No.:	122




Photograph No.:	5	Direction:	North
Description:	View of construction debris GCDD stall		



Photograph No.:	6	Direction:	West
Description:	View of tarping station		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/15/25	Time:	10:45 AM
Inspector:	Archie Tolar			Badge No.:	122



Photograph No.:	7	Direction:	South
Description:	View of tire storage container		



Photograph No.:	8	Direction:	North
Description:	View of MSW pile		