F05-01

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:	0310810003		
Address:	1711 Church Street				
City:	Evanston	Date:	7/25/25	Time:	9:00 AM
Inspector:	Archie Tolar			Badge No.:	122

Inspection Report

Inspection Type:

☒Complaint ☐Commercial ☐Industrial ☐Waste/Recycling ☐Asbestos ☐Demolition
☐ Other:

Observations and Comments:

Inspector Tolar investigated an odor complaint at Evanston Transfer Station. Juan Gonzalez, scale operator, was on site and was interviewed by Inspector Tolar. The weather was sunny and 85°F. There have been multiple complaints filed for smell at the site.

Inspector Tolar did a follow-up inspection on June 2nd, and July 15th, 2025. The site has installed new misters, and all systems were in operation. There was a pleasant aroma, and the sprayers could be seen spraying the deodorizer. Inspector Tolar drove within several blocks radius to determine if there was smells outside of the immediate area of the site. There was no evidence of smell or maldor at the site during the inspection. Inspector observed all doors open during a non-peak time of the day. Inspector advised Juan to keep the doors closed if the stall is not being used or business is slow. Juan appreciated this idea. The site was found to be complying at the time of the inspection.

The site is approximately one acre in size and contains a scale house, scales, and a transfer station building. Bordering the site are residential neighborhoods to the east and west, a business to the north, and Church Street to the south, where the site entrance/exit is located. The site accepts MSW.

Inspector Tolar will continue to monitor this site monthly.

Orkin serviced the location on July 22nd, 2025.

Outbound Tonnage for MSW for June 2025 was 7,214.33 tons (Zion Landfill & Orchard Hills)

Inbound Tonnage for MSW for June 2025 was 7425.07 tons

There were 10 tires in the storage bin. (Pomps)

This site will continue to be monitored on a regular basis to assure compliance.

RECEIVED
JAN 06 2026
IEPA
Division of Records Management
Releasable

☒ Photos Taken
☐ Warning Issued
☐ Citation Issued
☐ Follow-up Inspection Required

Signature: Archie Tolar JAN 26 2026

Reviewer: AMS


COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/25/25	Time:	9:00 AM
Inspector:	Archie Tolar			Badge No.:	122

Site Map

Photo does not depict current conditions at the site at the time of inspection.


N ↑



COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/25/25	Time:	9:00 AM
Inspector:	Archie Tolar			Badge No.:	122

Photograph Log



Photograph No.:	1	Direction:	North
Description:	Inspector parked at corner of Dodge/Church 1 block west of site		




Photograph No.:	2	Direction:	Northwest
Description:	Inspector Parked at Doge/Emerson 2 blocks north of site		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/25/25	Time:	9:00 AM
Inspector:	Archie Tolar			Badge No.:	122




Photograph No.:	3	Direction:	North
Description:	View of site misters spraying deodorizer		



Photograph No.:	4	Direction:	North/west
Description:	View of tarping station		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/25/25	Time:	9:00 AM
Inspector:	Archie Tolar			Badge No.:	122




Photograph No.:	5	Direction:	South
Description:	View of tire bin		



Photograph No.:	6	Direction:	North
Description:	View of worker cleaning lot		

COOK COUNTY
DEPARTMENT OF ENVIRONMENT AND SUSTAINABILITY
SOLID WASTE INSPECTION REPORT

Facility:	Evanston Transfer Station				
CCDEC ID:		IEPA ID or Other ID:		0310810003	
Address:	1711 Church Street				
City:	Evanston	Date:	7/25/25	Time:	9:00 AM
Inspector:	Archie Tolar			Badge No.:	122



Photograph No.:	7	Direction:	East
Description:	View of loading bay		



Photograph No.:	8	Direction:	North
Description:	View of MSW pile		